



OLENE S. WALKER
Governor
GAYLE F. McKEACHNIE
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

Supervisor QQZ

Inspection Report

Minerals Regulatory Program

Report Date: October 20, 2004

Mine Name: Strawberry River Quarry
Operator or Permittee Name:
Rock-It Stone Workd
Permittee Mailing Address:
P. O. Box 538, Heber City, UT 84032-0538

Permit number: S/013/008
Inspection Date: October 19, 2004

Inspector(s): Paul Baker and Doug Jensen

Other Participants: None

Permit Status: Active
Current Acreages:
Total Permitted (Bonded): About 3.5
Total Disturbed: About 3.5

Weather: Cloudy with recent rain, 40's
Inspection Start Time: 1:10 PM
Inspection End Time: 1:15 PM
Site location/Area Inspected (i.e. Pit #):
Drainage to the west of the quarry
Surface Ownership: Fee
Mineral Ownership: Fee
Mineral Mined: Stone
Type of Mine: Surface

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: October 19, 2004 Report Date: October 20, 2004
Page 2 of 2
S/013/008

Purpose of Inspection:

The operator said in a telephone conversation that the drainage to the west of the quarry had been reclaimed. I wanted to check this before approving a recently-submitted revised Notice of Intention to Commence Small Mining Operations.


Inspection Summary:

3. Protection of Drainages

Mr. Peatross told me he had cleaned out most of the fill in the drainage to the west of the stone quarry and that any remaining material had been washed out as the result of runoff from a heavy rain. Based on our observations, this appeared to be the case (Photo 1). It looked like some of the material that had been placed in the drainage washed out on to the road and placed to the north of the road when it was cleared. Some remained behind the berm shown in the photo. It is possible some of this fill went into the Strawberry River, but this was not clear.

The operator submitted a revised Notice of Intention to Commence Small Mining Operations but did not include right of entry for the area of the drainage. Since this area has now been reclaimed, it can be left outside the permitted area.

Inspector's Signature



Date: October 20, 2004

PBB:jb

Enclosures: Photo attachment

cc: Shannon Peatross, Operator

O:\M013-Duchesne\S0130008-strawberry\inspections\ins-10192004.doc

ATTACHMENT
Photograph

S/013/008, Strawberry River Quarry, Rock-It Stone

Inspection Dated: October 19, 2004; Report Dated: October 20, 2004



Photo 1. Drainage to the west of the quarry. To make a ramp to access the upper part of the quarry, fill had been placed against the escarpment in the center of this photo. The operator said he had removed most of the fill, and the rest was washed out by runoff from a large storm. The berm in the foreground is right next to the county road.